Back to Table of Contents

Background

NIST Handbook 44
Sec. 1.10 General
Code, G-UR.4.5.

VTM and LPG meters are frequently found by inspectors to not have security seals intact as required. Many times tickets will jam in the register forcing the operator to break the seal to remove the jammed ticket.

Policy

VTM and LPG meters, as well as all other commercial measuring devices, are required under Handbook 44 Sec. 1.10 General Code, G-UR.4.5. to be sealed with a security seal. Devices found missing a security seal should be marked incorrect and the enforcement guidelines in the policy and procedure book shall be followed.